

Certificate of Compliance

Certificate Number:

UL-US-L325350-11-12019002-2

Report Reference:

E325350-20091021

Issue Date:

2024-05-15

Issued to:

Tolomatic Inc 3800 County Road 116 Hamel, MN 55340-9342 United States

This certificate confirms that representative samples of:

NDMM2 - Incomplete Rotating Machines and Rotating Machine Parts - Component

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

UL 1004-1, 2nd Ed., Issue Date: 2012-09-19, Revision Date: 2018-08-07

Additional Information:

See UL Product iQ® at https://iq.ulprospector.com for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



UL Mark Certification Program Manager

Page 1 of 3



Certificate number UL-US-L325350-11-12019002-2

Report reference E325350-20091021

Date 2024-05-15

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Model	Product Description
%CSW/X3 V23	Incomplete Motor Parts
%CSW/X3 V23W	Incomplete Motor Parts
%CSW/X3 V24	Incomplete Motor Parts
%CSW/X3 V24W	Incomplete Motor Parts
%CSW/X3 V43	Incomplete Motor Parts
%CSW/X3 V43W	Incomplete Motor Parts
%CSW/X3 V44	Incomplete Motor Parts
%CSW/X3 V44W	Incomplete Motor Parts
CSWL MV23	Incomplete Motor Parts
CSWL MV23W	Incomplete Motor Parts
CSWL MV43	Incomplete Motor Parts
CSWL MV43W	Incomplete Motor Parts
GSWA04 MV22	Incomplete Motor Parts
GSWA04 MV23	Incomplete Motor Parts
GSWA04 MV23	Incomplete Motor Parts
GSWA04 MV42	Incomplete Motor Parts
GSWA04 MV43	Incomplete Motor Parts
GSWA33 MV23	Incomplete Motor Parts
GSWA33 MV23WC	Incomplete Motor Parts
GSWA33 MV43	Incomplete Motor Parts
GSWA33 MV43WC	Incomplete Motor Parts
GSWA44 MV23	Incomplete Motor Parts
GSWA44 MV23WC	Incomplete Motor Parts
GSWA44 MV43	Incomplete Motor Parts
GSWA44 MV43WC	Incomplete Motor Parts
IMA22 MV21	Incomplete Motor Parts
IMA22 MV23	Incomplete Motor Parts
IMA22 MV41	Incomplete Motor Parts
IMA22 MV43	Incomplete Motor Parts
IMA33 MV21	Incomplete Motor Parts
IMA33 MV23	Incomplete Motor Parts
IMA33 MV24	Incomplete Motor Parts
IMA33 MV41	Incomplete Motor Parts
IMA33 MV43	Incomplete Motor Parts
IMA33 MV44	Incomplete Motor Parts
IMA44 MV22	Incomplete Motor Parts
IMA44 MV23	Incomplete Motor Parts
IMA44 MV24	Incomplete Motor Parts



UL Mark Certification Program Manager



Certificate number UL-US-L325350-11-12019002-2

Report reference E325350-20091021

Date 2024-05-15

IMA44 MV42	Incomplete Motor Parts
IMA44 MV43	Incomplete Motor Parts
IMA44 MV44	Incomplete Motor Parts
IMA55 MV23	Incomplete Motor Parts
IMA55 MV43	Incomplete Motor Parts
IMAS*22 MV21	Incomplete Motor Parts
IMAS*22 MV23	Incomplete Motor Parts
IMAS*22 MV41	Incomplete Motor Parts
IMAS*22 MV43	Incomplete Motor Parts
IMAS*33 MV21	Incomplete Motor Parts
IMAS*33 MV23	Incomplete Motor Parts
IMAS*33 MV41	Incomplete Motor Parts
IMAS*33 MV43	Incomplete Motor Parts
SWA/B 3 A3	Incomplete Motor Parts
SWA/B 3 A3WC	Incomplete Motor Parts
SWA/B 3 B3	Incomplete Motor Parts
SWA/B 3 B3WC	Incomplete Motor Parts
SWA/B 4 A2	Incomplete Motor Parts
SWA/B 4 A2WC	Incomplete Motor Parts
SWA/B 4 A3	Incomplete Motor Parts
SWA/B 4 A3WC	Incomplete Motor Parts
SWA/B 4 A4	Incomplete Motor Parts
SWA/B 4 A4WC	Incomplete Motor Parts
SWA/B 4 B2	Incomplete Motor Parts
SWA/B 4 B2WC	Incomplete Motor Parts
SWA/B 4 B3	Incomplete Motor Parts
SWA/B 4 B3WC	Incomplete Motor Parts
SWA/B 4 B4	Incomplete Motor Parts
SWA/B 4 B4WC	Incomplete Motor Parts

David Piecuch

UL Mark Certification Program Manager





Certificate of Compliance

Certificate Number:

UL-CA-L325350-31-12019002-2

Report Reference:

E325350-20091021

Issue Date:

2024-05-15

Issued to:

Tolomatic Inc 3800 County Road 116 Hamel, MN 55340-9342 **United States**

This certificate confirms that representative samples of:

NDMM8 - Incomplete Rotating Machines and Rotating Machine Parts Certified for Canada - Component

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

CSA C22.2 NO. 100, 7th Ed., Issue Date: 2014-07-01, Revision Date: 2017-04-01

Additional Information:

See UL Product iQ® at https://iq.ulprospector.com for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



UL Mark Certification Program Manager



Certificate number UL-CA-L325350-31-12019002-2

Report reference E325350-20091021

Date 2024-05-15

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Model	Product Description
%CSW/X3 V23	Incomplete Motor Parts
%CSW/X3 V23W	Incomplete Motor Parts
%CSW/X3 V24	Incomplete Motor Parts
%CSW/X3 V24W	Incomplete Motor Parts
%CSW/X3 V43	Incomplete Motor Parts
%CSW/X3 V43W	Incomplete Motor Parts
%CSW/X3 V44	Incomplete Motor Parts
%CSW/X3 V44W	Incomplete Motor Parts
CSWL MV23	Incomplete Motor Parts
CSWL MV23W	Incomplete Motor Parts
CSWL MV43	Incomplete Motor Parts
CSWL MV43W	Incomplete Motor Parts
GSWA04 MV22	Incomplete Motor Parts
GSWA04 MV23	Incomplete Motor Parts
GSWA04 MV23	Incomplete Motor Parts
GSWA04 MV42	Incomplete Motor Parts
GSWA04 MV43	Incomplete Motor Parts
GSWA33 MV23	Incomplete Motor Parts
GSWA33 MV23WC	Incomplete Motor Parts
GSWA33 MV43	Incomplete Motor Parts
GSWA33 MV43WC	Incomplete Motor Parts
GSWA44 MV23	Incomplete Motor Parts
GSWA44 MV23WC	Incomplete Motor Parts
GSWA44 MV43	Incomplete Motor Parts
GSWA44 MV43WC	Incomplete Motor Parts
IMA22 MV21	Incomplete Motor Parts
IMA22 MV23	Incomplete Motor Parts
IMA22 MV41	Incomplete Motor Parts
IMA22 MV43	Incomplete Motor Parts
IMA33 MV21	Incomplete Motor Parts
IMA33 MV23	Incomplete Motor Parts
IMA33 MV24	Incomplete Motor Parts
IMA33 MV41	Incomplete Motor Parts
IMA33 MV43	Incomplete Motor Parts
IMA33 MV44	Incomplete Motor Parts
IMA44 MV22	Incomplete Motor Parts
IMA44 MV23	Incomplete Motor Parts



UL Mark Certification Program Manager



Certificate number UL-CA-L325350-31-12019002-2

Report reference E325350-20091021

Date 2024-05-15

IMA44 MV24	Incomplete Motor Parts
IMA44 MV42	Incomplete Motor Parts
IMA44 MV43	Incomplete Motor Parts
IMA44 MV44	Incomplete Motor Parts
IMA55 MV23	Incomplete Motor Parts
IMA55 MV43	Incomplete Motor Parts
IMAS*22 MV21	Incomplete Motor Parts
IMAS*22 MV23	Incomplete Motor Parts
IMAS*22 MV41	Incomplete Motor Parts
IMAS*22 MV43	Incomplete Motor Parts
IMAS*33 MV21	Incomplete Motor Parts
IMAS*33 MV23	Incomplete Motor Parts
IMAS*33 MV41	Incomplete Motor Parts
IMAS*33 MV43	Incomplete Motor Parts
SWA/B 3 A3	Incomplete Motor Parts
SWA/B 3 A3WC	Incomplete Motor Parts
SWA/B 3 B3	Incomplete Motor Parts
SWA/B 3 B3WC	Incomplete Motor Parts
SWA/B 4 A2	Incomplete Motor Parts
SWA/B 4 A2WC	Incomplete Motor Parts
SWA/B 4 A3	Incomplete Motor Parts
SWA/B 4 A3WC	Incomplete Motor Parts
SWA/B 4 A4	Incomplete Motor Parts
SWA/B 4 A4WC	Incomplete Motor Parts
SWA/B 4 B2	Incomplete Motor Parts
SWA/B 4 B2WC	Incomplete Motor Parts
SWA/B 4 B3	Incomplete Motor Parts
SWA/B 4 B3WC	Incomplete Motor Parts
SWA/B 4 B4	Incomplete Motor Parts
SWA/B 4 B4WC	Incomplete Motor Parts



UL Mark Certification Program Manager

